

Visual representation of Horizontal Load factors on guardrail

Affected ProBuilt posts tested to service load plus 1.49 safety factor on top of service load

